



Visitor Centre and Lodge

Extension of existing Lodge to create multi-use spaces including meeting and research rooms, for visitors, educational groups and the wider community along with a garden area for displays and interpretation. Improved accommodation and reception areas for the Bereavement Services.



Infrastructure repairs

Re-construction of carriageways to an appropriate high quality standard with associated drainage repairs.



Robson Road Entrance

New pedestrian entrance, with enhancements to the streetscape, (subject to landowner agreements).


St Stephen's Chapel

Conservation and repair of the Chapel, including the incorporation of services and toilets to enable use for a wide range of events, displays, and functions. Improved access.



Boundary repairs

Repairs and conservation of boundary railings and gates.



Conservation of Listed Monuments

Repairs and stabilisation of 16 significant Listed monuments deemed "heritage at risk".



Infrastructure repairs

Re-construction of path and drainage (St Mary at Hill path).



Path Improvements

Improve drainage and surfacing, with an informal gravel finish (Doulton path).



Ongoing management

Continue to manage and control scrub to improve bio-diversity, protect monuments, and enable better access to graves.



Grass management

Continue to manage selected areas to improve bio-diversity and wildflowers.



Enhanced views

Continue to manage trees, including sycamore and ash, to open up key views.



Monument repairs

Conserve and stabilise selected monuments, along important paths (Ship, Beeton and Doulton paths).



Hubbard Road Entrance

Re-instate gates as pedestrian entrance, with enhancements to the streetscape, (subject to agreements with grave owners).

